CARE INSTRUCTIONS
FOR OUR APPAREL



T-SHIRTS

Do not dryclean; do not bleach. Tumble dry on low heat; Iron, steam or dry on low heat. Machine wash cold (max 30°C or 90°F), with similar colors.



SWEATSHIRTS

Machine wash cold (max 30°C or 90°F). Use non-chlorine bleach as needed. Tumble dry on low heat. Do not iron, do not dryclean.



HOODIES

Tumble dry on medium heat. Iron, steam or dry on low heat. Do not dryclean. Machine wash cold (max 30°C or 90°F). Use non-chlorine bleach as needed.

Our garments use direct-to-garment (DTG) printing. This process sometimes leaves behind a slight but distinct odor, a by-product of the printing process. This is a normal occurrence in the DTG printing industry, and the smell disappears completely after one wash.

These care instructions will help you keep your purchase looking its best for as long as possible!